


Mahindra First Choice Wheels Certification Report



2018 HONDA WR-V(2017-2020) S MT PETROL

Gurgaon | 9493 km | Petrol | Manual | Red Colour | 1st Owner

- ✔ Eligible for Warranty
- ✔ 200+ Points Inspected



Overall
Excellent Buy 🙌

M Mahajan
Head Certification & Warranty - MFCWL

Explore this car in website [View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **200+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

**Car&Bike Superstore
Gurgaon**

Registration Month

June

Registration Year

2019

Color

Red

Odometer Reading(km)

9493

Registration Number

DL8CXXXXXX

No of Owners

1

Chassis Number

LJ40XXXXX

Engine Number

B430XXXXX

Insurance Status

Available

Accidental / Flooded

**Non-Accidental and Non-
flooded**

CNG Validity Inspection Date

Not Applicable

RC Status

Available

PUC Certificate

Not Available

Keys Availability

**One Key Available And
Good**

Transfer papers availability

Available

CNG Hydro Test Validity
Certificate

Not Applicable

Vehicle Status

Certified

Remarks

•

[View in Website](#)

Front Bumper

Condition : Good

Visible Repaint

Grill

Condition : Excellent

Good Condition

Emblem

Condition : Excellent

Good Condition

Windscreen glass Front

Condition : Excellent

Good Condition

Bonnet

Condition : Good

Visible Repaint

Bonnet Functionality

Condition : Excellent

Good Condition

RH Side Apron

Condition : Excellent

Good Condition

Right Running Board

Condition : Excellent

Good Condition

Right Fender

Condition : Good

Visible Repaint

Front Right Door

Condition : Good

Visible Repaint

Right Front Door Functionality

Condition : Excellent

Good Condition

Front Right Door handle

Condition : Excellent

Good Condition

Front Right Window Glass

Condition : Excellent

Good Condition/Same Make

Rear Right Door

Condition : Excellent

Light/Short Scratches-under 2

Right Rear Door Functionality

Condition : Excellent

Good Condition

Rear Right Door handle

Condition : Excellent

Good Condition

Rear Right Window Glass

Condition : Excellent

Good Condition/Same Make

RH A Pillars

Condition : Excellent

Good Condition

Exterior (Continued...)

RH B Pillars

Condition : **Excellent**

Good Condition

RH C Pillars

Condition : **Excellent**

Good Condition

Right Quarter Panel

Condition : **Excellent**

Good Condition

Right Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Right Side Power Mirror + Casing

Condition : **Excellent**

Not Applicable

Front right tyre

Condition : **Satisfactory**

25-40%

Alloy Wheels Present?

Condition : **Yes**

Yes

Wheel Front RHS

Condition : **Excellent**

Good Condition

Rear right tyre

Condition : **Satisfactory**

25-40%

Wheel Rear RHS

Condition : **Excellent**

Good Condition

Windscreen glass Back

Condition : **Satisfactory**

Light/Short Scratches

Trunk

Condition : **Excellent**

Good Condition

Trunk Functionality

Condition : **Excellent**

Good Condition

Rear Bumper

Condition : **Good**

Visible Repaint

Dickey Shock absorber

Condition : **Excellent**

Good Condition

Spare tyre (stephney)

Condition : **Good**

Same Make/ Good & > 60% life

Spare Wheel / Cover

Condition : **Excellent**

Not Applicable

Number Plate (Front & Rear)

Condition : **Excellent**

RTO Format

Exterior (Continued...)

LH A Pillars

Condition : **Excellent**

Good Condition

LH B Pillars

Condition : **Excellent**

Good Condition

LH C Pillars

Condition : **Excellent**

Good Condition

Left Running Board

Condition : **Excellent**

Good Condition

Left Fender

Condition : **Excellent**

Good Condition

Left Front Door

Condition : **Excellent**

Good Condition

Front Left Door Functionality

Condition : **Excellent**

Good Condition

Front Left Door handle

Condition : **Excellent**

Good Condition

Front Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Left Side View Mirror + Casing

Condition : **Excellent**

Good Condition

Left Side Power Mirror + Casing

Condition : **Excellent**

Not Applicable

Rear Left Door

Condition : **Excellent**

Good Condition

Rear Left Door Functionality

Condition : **Excellent**

Good Condition

Rear Left Door handle

Condition : **Excellent**

Good Condition

Left Quarter Panel

Condition : **Excellent**

Good Condition

Rear Left Window Glass

Condition : **Excellent**

Good Condition/Same Make

Fuel Cap

Condition : **Excellent**

Working Properly

Front Left tyre

Condition : **Satisfactory**

40%-60%

Exterior (Continued...)

Wheel Front LHS

Condition : **Excellent**

Good Condition

Rear Left tyre

Condition : **Satisfactory**

25-40%

Wheel Rear LHS

Condition : **Excellent**

Good Condition

LH Side Apron

Condition : **Excellent**

Good Condition

Frame or Underbody

Condition : **Excellent**

No panel Replaced

Reverse Camera & Reverse Parking Sensor

Condition : **Excellent**

Functional

Roof

Condition : **Excellent**

Good Condition

Front Windows Type

Condition : **Power Windows**

Power Windows

Front Right Window Function

Condition : **Excellent**

Smooth Operation

Front Left Window Function

Condition : **Excellent**

Smooth Operation

Rear Windows Type

Condition : **Power Windows**

Power Windows

Rear Right Window Function

Condition : **Excellent**

Smooth Operation

Rear Left Window Function

Condition : **Excellent**

Smooth Operation

Windscreen Wiper Front

Condition : **Excellent**

All speeds working properly

Windscreen Wiper Rear

Condition : **Excellent**

Not Applicable

Windscreen Jets

Condition : **Excellent**

Good Condition

Parking Lights Front

Condition : **Excellent**

Good Condition

Parking Lights Rear

Condition : **Excellent**

Good Condition

Exterior (Continued...)

Right Tail Light

Condition : **Excellent**

Good Condition

Left Tail Light

Condition : **Excellent**

Good Condition

Rear Left Indicator

Condition : **Excellent**

Good Condition

Rear Right Indicator

Condition : **Excellent**

Good Condition

Front Left Indicator

Condition : **Excellent**

Good Condition

Front Right Indicator

Condition : **Excellent**

Good Condition

Left Headlight (Both Points)

Condition : **Excellent**

Good Condition

Right Headlight (Both Points)

Condition : **Excellent**

Good Condition

Fog lamps

Condition : **Excellent**

Not Applicable

Wheel Cap

Condition : **Excellent**

Not Applicable

RHS Front Door Trim

Condition : **Excellent**
Good Condition

RHS Rear Door Trim

Condition : **Excellent**
Good Condition

Rubber Beading Front RHS

Condition : **Excellent**
Good Condition

Rubber Beading Rear RHS

Condition : **Excellent**
Good Condition

LHS Front Door Trim

Condition : **Excellent**
Good Condition

LHS Rear Door Trim

Condition : **Excellent**
Good Condition

Rubber Beading Front LHS

Condition : **Excellent**
Good Condition/Same Make

Rubber Beading Rear LHS

Condition : **Excellent**
Good Condition/Same Make

Carpets

Condition : **Excellent**
Good Condition

Roof Inside

Condition : **Excellent**
Good Condition

Driver Seat Sliding Front to Back

Condition : **Excellent**
Good Condition

Driver Seat recliner

Condition : **Excellent**
Good Condition

Driver Seat Up Down

Condition : **Excellent**
Good Condition

Passenger Seat Sliding Front to Back

Condition : **Excellent**
Good Condition

Passenger Seat recliner

Condition : **Excellent**
Good Condition

Passenger Seat Up Down

Condition : **Excellent**
Good Condition

Safety belts inertia locking system Driver Seat

Condition : **Excellent**
Good Condition

Safety belts inertia locking system Passenger

Condition : **Excellent**
Good Condition

Interior (Continued...)

Dash Board

Condition : **Excellent**
Good Condition

Sunroof System

Condition : **Excellent**
Not Applicable

Steering Mounted Controls

Condition : **Excellent**
Good Condition

Inside Rear View mirror

Condition : **Excellent**
Good Condition

Driver Seat Condition

Condition : **Excellent**
Good Condition

Passenger Seat Condition

Condition : **Excellent**
Good Condition

Rear Seat Condition

Condition : **Excellent**
Good Condition

**Instrument panel gauges:
Odometer**

Condition : **Excellent**
Good Condition

**Instrument panel Warning
Lights**

Condition : **Excellent**
Warning Lights Off - Good

Instrument panel gauges: Fuel

Condition : **Excellent**
Good Condition

**Instrument panel gauges:
Tachometer**

Condition : **Excellent**
Good Condition

**Instrument panel gauges:
Temperature**

Condition : **Excellent**
Good Condition

Horn

Condition : **Excellent**
Good Condition

Combination Switch

Condition : **Excellent**
Good Condition

Stereo Controls

Condition : **Excellent**
Good Condition

Charger/USB Port

Condition : **Excellent**
Good Condition

Interior lights

Condition : **Excellent**
Good Condition

Hazard lights

Condition : **Excellent**
Good Condition

Interior (Continued...)

Trunk Light

Condition : **Excellent**
Good Condition

Music System

Condition : **Excellent**
Good Condition

Music system type

Steering Wheel Mounted Music Control

Speakers

Condition : **Excellent**
Good Condition

Defogger

Condition : **Excellent**
Good Condition

Central Locking System

Condition : **Excellent**
Good Condition

AC cooling (Check undershade)

Condition : **Excellent**
Good Condition

Heating

Condition : **Excellent**
Good Condition

Air distribution (AC Vents)

Condition : **Excellent**
Good Condition

Recirculation/ Fresh air

Condition : **Excellent**
Good Condition

Steering Type

Power Steering

Power Steering Type

Electronic

Steering condition

Condition : **Excellent**
Good Condition

Air Bags

Condition : **Excellent**
Functional

Hand Brake

Condition : **Excellent**
Working less than 4 notches

CNG/LPG kit - OEM/Aftermarket

Condition : **Excellent**
Not Applicable

Jack And Tommy (Tool Kit)

Condition : **Excellent**
Available

Battery

Condition : **Excellent**

Good Condition

Alternator

Condition : **Excellent**

Good Condition

Starter Motor

Condition : **Excellent**

Good Condition

Fuel Pump

Condition : **Excellent**

Good Condition

AC Compressor

Condition : **Excellent**

Good Condition

Condenser Fan

Condition : **Excellent**

Good Condition

Blower motor

Condition : **Excellent**

Good Condition

**Steering / Column with motor
Rattling Noise**

Condition : **Excellent**

Working Properly

Suspension Arms

Condition : **Excellent**

All rubber boot & bushing ok

Front struts (Shock Absorber)

Condition : **Excellent**

No Leakage & Rubber boots ok

Rear Shock Absorber/Spring

Condition : **Excellent**

No Leakage & Rubber boots ok

Stabiliser Bar & Other bushes

Condition : **Excellent**

Good Condition

Link Rods (Ball joints)

Condition : **Excellent**

No Noise & Rubber boots ok

ABS

Condition : **Excellent**

Working

Brake Pedal

Condition : **Excellent**

Operating Properly

Accelerator

Condition : **Excellent**

Working Properly

Check Front Brake Efficiency

Condition : **Excellent**

Operating Efficiently

Check Rear Brake Efficiency

Condition : **Excellent**

Operating Efficiently

Engine & Transmission (Continued...)

Master Cylinder & Booster

Condition : **Excellent**

Good Condition

**Gearshift lever
Automatic/Manual**

Condition : **Excellent**

Good Condition

Clutch Engagement

Condition : **Excellent**

More than 50% life

Axle Noise

Condition : **Excellent**

No noise & Boot okay

Front Wheel bearings

Condition : **Excellent**

Good Condition

Rear Wheel bearings

Condition : **Excellent**

Good Condition

Differential

Condition : **Excellent**

Good Condition

Alignment

Condition : **Excellent**

Good Condition

Balancing

Condition : **Excellent**

Good Condition

**Transmission Oil (Manual/
Automatic)**

Condition : **Excellent**

Oil Level Condition OK

**Engine and transmission
mountings**

Condition : **Excellent**

Good Condition

Abnormal Engine Noise

Condition : **Excellent**

No Noise

Back Compression

Condition : **Excellent**

Back Compression Not Present

Head Gasket leakage/replaced

Condition : **Excellent**

Good Condition

Gasket - tappet cover

Condition : **Excellent**

Good Condition

**Engine oil leaks From
Bottom/Oil Sump**

Condition : **Excellent**

Good Condition

Silencer

Condition : **Excellent**

Good Condition

Catalytic Converter

Condition : **Excellent**

Good Condition

Engine & Transmission (Continued...)

Engine Smoke Colour

Condition : **Excellent**

No colour

Air Filter

Condition : **Excellent**

Cleaned/Replaced

Radiator

Condition : **Excellent**

Good Condition

Condenser

Condition : **Excellent**

Good Condition

Engine oil & Oil Filter

Condition : **Excellent**

Good Condition

Coolant

Condition : **Excellent**

Good Condition

Brake Oil

Condition : **Excellent**

Good Condition

Hose Pipe

Condition : **Excellent**

Good Condition

Alternator Drive Belt

Condition : **Excellent**

Good Condition

Water Pump

Condition : **Excellent**

Good Condition

Tappet Noise

Condition : **Excellent**

Working Smoothly

Turbo Charger

Condition : **Excellent**

Not Applicable

Heater Plugs (in Diesel)

Condition : **Excellent**

Not Applicable

Spark Plugs (in Petrol)

Condition : **Excellent**

Good Condition

Radiator Fan

Condition : **Excellent**

Temperature Sensor Working

Ignition Coil (petrol only)

Condition : **Excellent**

Good Condition

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Good Condition

Fuel Tank and Pipes

Condition : **Excellent**

Good Condition

Engine & Transmission (Continued...)

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good Condition

Fuel Injectors

Condition : **Excellent**

Working Smoothly

Vehicle Images

Front Side



27 Apr 2023 15:07:10

Lat 28.4617981, Long 77.0690369

Front Right Side



27 Apr 2023 15:07:19

Lat 28.4619407, Long 77.0695783

Front Right Tyre



27 Apr 2023 15:07:26

Lat 28.4618625, Long 77.0694387

Right Side



27 Apr 2023 15:07:31

Lat 28.4618679, Long 77.0694572

Rear Right Tyre



27 Apr 2023 15:07:38

Lat 28.4618342, Long 77.0693694

Rear Right Side



27 Apr 2023 15:07:43

Lat 28.4618266, Long 77.0693445

Back Side



27 Apr 2023 15:07:48

Lat 28.4617776, Long 77.0692631

Rear Left Side



27 Apr 2023 15:07:53

Lat 28.4616367, Long 77.0691833

[View this car in Website](#)

Rear Left Tyre



27 Apr 2023 15:08:03

Lat 28.461645, Long 77.0691483

Left Side



27 Apr 2023 15:08:09

Lat 28.4616489, Long 77.0691471

Front Left Tyre



27 Apr 2023 15:08:15

Lat 28.461663, Long 77.0691423

Front Left Side



27 Apr 2023 15:08:21

Lat 28.4616695, Long 77.0691519

Odometer



27 Apr 2023 15:09:27

Lat 28.4617923, Long 77.0692098

Videos

Car Exterior Video

<https://tinyurl.com/2plzznct>

Car Engine Video

<https://tinyurl.com/2psduajl>